

E-918



ALCO INC. HEAD OFFICE
6925 - 104 Street, Edmonton, Alberta T6H 2L5
Office: (780) 435-3502
Website: www.alcoinc.ca

November 5, 2021
Gilliss Casing Services
P.O. Box 1055
Estevan, SK.
S4A 2H7

Certificate of Conformance

CUSTOMER:	Gilliss Casing Services
CUSTOMER EQUIPMENT # :	2107110
CUSTOMER RIG # :	N/A
EQUIPMENT DESCRIPTION:	RT Single Joint Casing Elevator
MODEL AND RATING: <u>5 Tons</u>	9 5/8" - 5 Ton (4448-daN)
INSPECTION COMPANY / REPORT #:	Alco / H -N/A
ALCO ENGINEERING FILE #:	71668-4-E
ALCO WORK ORDER # :	71668-4


This document specifies that all parts and/or assemblies for the equipment referenced above are sold under the manufacturer's warranty.

The above referenced items are to be used according to the manufacturer's directions and ratings. Alco assumes no responsibility for defective parts or assemblies or any costs associated with their repair due to normal use or misuse.

Manufacture's documentation indicate a load test to 1.5 times this component's rating has been done. Material ductility requirements conform to those specified by the American Petroleum Institute's (API) section 8c.

A CAODC Recommended Practice Level IV inspection is typically required after: 500 operating days.

2021-11-05
Brian Kulak, P.Eng
Engineering Manager
Alco Inc.



PERMIT TO PRACTICE	
ALCO INC., GENERAL PARTNER OF THE ALCO LIMITED PARTNERSHIP	
RM SIGNATURE:	
RM APEGA ID #:	30312
DATE:	Nov 5 2021
PERMIT NUMBER: P010702	
The Association of Professional Engineers and Geoscientists of Alberta (APEGA)	